



Week:	September 1 – 6,	2014	Project No:	1305
Rain Days/Weather Conditions:		Rained 1.4" Sunday night & 0.2" on Tuesday (Burkesville gauge).		
Personnel on-site:		EcoGro/Ridgewater: John Arthur, Tony Berry, Tom Cutter, Eric Dawalt, Jim Hanssen, John Linder, Chad Relinski, Brad Redmon, Russ Turpin. Stantec: George Athanasakes (Wednesday) for site visit and Monthly Progress Meeting		
Equipment on-site:		Komatsu PC 160 w/ hyd. thumb, PC 360 w/ hyd. thumb, Terex TA27, Bobcat T300		
Material deliveries to project site:		■ ~4	10 ton spawning gravel	
Work performed	this week:	M Signal	et with KDFWR Project Managonthly On-site Progress Meetin creened rock (6"+) from Corps (cavated and built 300' of mair djacent braids: Sta. 149+40 to 152+40. Cavated channel from 147+00 uilding adjacent floodplain berm stalled ~150' of groundwater custon existing grade) with plastic bil area from LT St. 144+00 to 1 atchery Creek stream flow. Leared trees in excavation area (16+75 and Sta. 106+60 to 109+60) emoved (cut) invasive species thin PPC from ~Sta. 121+00 to 106+40 to 109+00. Inished redesigning step pool a lew survey data at tie-in to Cumles to Corps Engineering persor	disposal area for 2½ days. In channel and finished to149+00 and started to149+00 and started totoff trench/wall (up to 15' chiner and clay in sandy 45+50 to reduce loss of s from Rt. Sta. 113+50 to -00. (mostly autumn olive) 138+00, and from ~Sta. dignment and profile due to berland River. Sent CAD
Erosion & sedin installed:	nent controls	do	stalled temporary seed on all downstream of Campground Roakcavation Sites 1-4.	
Work scheduled	d for next week:	le e>	nish channel construction from aving road open at 149+00 for ccavation is finished. art constructing braided "D" changed 11+00. continue removing (cutting) inva- cart delivering boulders for step	vehicle access until Corps annel from 135+00 to asive species.
·	or two weeks ahead:	CONTRACTOR	onstruct "D" channel from 129+ ontinue invasives removal (cutt ontinue delivering boulders for	.00 to 141+00. ing). step pools.
General Comme	ents:		orps excavation sites are comp ady for Corps contractor to beg	
Prepared by: Eric Dawalt, P.E. Date: 9-8-14				





Pictures from this week's construction:



Sand layer (light brown) below clay layer (dark brown) in excavation area for new stream channel (looking left at ~Sta. 147+00).



Installing plastic liner and clay fill in groundwater cutoff trench/wall to reduce loss of stream flow due to sand layer (looking downstream ~LT Sta. 145+00).







Excavated channel (looking upstream from ~Sta. 148+50).



Constructed channel (looking downstream ~Sta. 151+00).







Constructed pool with overhanging habitat structure of wood and rock (looking downstream at outer bank).